

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED

JAN 24 2000

DIVISION OF
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-99 To (mo./yr.) 12-31-99
2. DOGM File Number (Mine No): 39100110
3. Mine Name: NINE MILE QUARRY
4. Mineral(s) Mined (or permitted to mine): Limestone (Building Stone)
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
NE 1/4, NE 1/4, NE 1/4, Section 16, Township 19S, Range 2E
____ 1/4, ____ 1/4, ____ 1/4, Section ____ , Township ____ , Range ____
____ 1/4, ____ 1/4, ____ 1/4, Section ____ , Township ____ , Range ____
7. Name of Operator or Company: DANNY L BOWN
8. Permanent Street Address: 595 E 600 S
City, State, Zip: MANTI, UT, 84642
Phone: 1-435-835-7542 Fax: _____
9. Company Representative (or designated operator):
Name: DANNY L BOWN
Title: Leasee
Business Address: 595 E 600 S
City, State, Zip: MANTI UT, 84642
Phone: 1-435-835-7542 Fax: _____

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? -1999
3. If yes - how much ore or mineral was mined? 1000 TON

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
QUARRING OF BUILDING STONE ~~RECLAIM~~
2000-3000 TON OF MATERIAL MOVED TO
PRODUCE USABLE BUILDING STONE
1/3 OF NEW SURFACE WAS DISTURBED
5. How much **additional acreage** was disturbed during the past year? 1/3 ACRE
6. How much acreage was **reclaimed** during the past year? 1/3 ACRE
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
ACREAGE WAS DOZED AS CLOSE AS POSSIBLE
TO OLD SURFACE & LEVELED AS CLOSE AS POSSIBLE
TO OLD CONTOUR OF LAND
8. What is the **total disturbed acreage of entire project** at years end? 1/3 - 1/2
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
WE HAVE PLANS TO RECLAIM ALL BUT - HAVING
AROUND ONE ACRE ACTIVE OR NOT RECLAIMED

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

DANNY L BOWN

Title of Operator:

Lessee - operator

Signature of Operator:

Danny L Bown

Date:

1-8-2000